



Warren-Sugarbush Airport  
(0B7) Transient Aircraft  
Information Version - 3/18

Airport Elevation 1,470'



**CHECK NOTAMS/AFD**  
for current information  
**Note: Rapidly Rising**  
**Terrain All Quadrants**

Secondary IP from East/45 degree  
entry for downwind RY 4

**Use Caution: Extensive**  
**glider and glider training**  
**activity on and in the**  
**vicinity of the airport.**  
**Touch & go landings not**  
**permitted.**

Secondary IP from East/45 degree  
entry for downwind RY 22

Tower/FBO Building

Transient Aircraft Parking

Primary Initial Point (IP) –  
Midfield X-W Entry from  
Warren Pinnacle

Private Hangar/Taxiway

Private Blue T Hangars

22

4

Dump Rd

Airport Rd

4 Corners


Roxbury Gap Rd

**CTAF – 123.0 Right Traffic**  
**RY 4, Left Traffic RY 22**

Brook Rd

Phone: 802-496-2290  
Email: [airportmanager@sugarbushsoaring.com](mailto:airportmanager@sugarbushsoaring.com)

**Legend**

- Standard Traffic Pattern
-  2 windsocks – one at midfield, one on top of Tower Bldg
- ..... Roads